



CONDITION REPORT

Stock: 16720
Unit: 413392S
Customer: 09-07-00-9SJM
Lot:



Date: 08/08/2023 06:00 AM
Seller: US GENERAL SERVICES
 ADMINISTRATION #G00193
Phone/Fax: (0) -(0) -
Sale Date:

Year 2017	Make FORD	Model ESCAPE S	Body Type Sport Utility	VIN 1FMCU0F76HUA30108
Drive FWD	Ext Color White	Int Color Gray	Int Material Cloth	Sound AM/FM
Fuel Gas	Mileage 63210	Odo. Type Digital	Engine 4-Cyl. 2.5Liters	Transmission Automatic
Doors 4	License Plate G413392S	License St	Plates 2	Plate Expires
				End of Term

- Accessories:** Stereo, (AM/FM Radio) Keyless entry (Left)
- Interior:** Power mirrors, Steering wheel controls, Tilt steering wheel, Side airbags - front, Power locks, Pass-through rear seat, Power windows, Cd player, Cruise control, Bluetooth connection, Rear floor mats, Pass. air bag, Driver air bag, Mp3 player, Traction control, Rear defroster, Seat trim (Cloth)
- Exterior:** Child safety locks, Wheels front left, (Steel) Wheels front right, (Steel) Spare tire, (Space Saver) Wheels rear left (Steel)
- Equipment:** Automatic headlights, Intermittent wipers, Engine immobilizer, Antilock brake system, Power steering, Power brakes, Air conditioner, Daytime running lights, Brake assist system, Front wheel drive, Smart key (1)
- Electronics:** Telematics, Trip computer, Reverse camera, Tire pressure monitor system
- Other:** Motor fuel type (Gas) , Cylinders (4) , Transmission (Automatic Transmission)

Notification:

Arrival: 08/03/2023

Visual:

Body:

Mechanical:

Writer: Erik Romer

Approval:

Complete: 08/03/2023

Revised:

Driveable: Yes

Visual Frame

Damage:

Book Value: \$13175.00

Tires	<i>Left</i>	<i>Right</i>
<i>Front</i>	07/32in Other P235/55HR17	07/32in Other P235/55HR17
<i>Rear</i>	09/32in Other P235/55HR17	09/32in Other P235/55HR17
<i>Spare</i>		



AutoGrade
 Grade 3.8 Average
[About AutoGrade](#)

Announcements:

Notes:

Inspection Date	Description	Approved	Repaired	Material Estimate	Labor Hours	Labor Estimate	Paint Hours	Paint Estimate	Sublet Estimate
<i>Chargeable</i>									
08/07/2023	Front bumper cover chipped - 10 or more. Refinish.			0.00	0.00	0.00	0.00	0.00	0.00
08/07/2023	Left drip rail peeling - GR 12in. Refinish.			0.00	0.00	0.00	0.00	0.00	0.00
08/07/2023	Lf seat cushion stained			0.00	0.00	0.00	0.00	0.00	0.00

	- Permanent. Detail.						
08/07/2023	Lr seat cushion stained	0.00	0.00	0.00	0.00	0.00	0.00
	- Permanent. Detail.						
08/07/2023	Rf seat cushion stained	0.00	0.00	0.00	0.00	0.00	0.00
	- Permanent. Detail.						
08/07/2023	Rr door chipped	0.00	0.00	0.00	0.00	0.00	0.00
	- 6. Touch Up.						
08/07/2023	Windshield cracked	0.00	0.00	0.00	0.00	0.00	0.00
	- Drivers side. 1 to 2in. Repair.						
Subtotal:		\$0.00	0.00	\$0.00	0.00	\$0.00	\$0.00
Deductible							
Subtotal:		\$0.00	0.00	\$0.00	0.00	\$0.00	\$0.00
Nonchargeable							
Subtotal:		\$0.00	0.00	\$0.00	0.00	\$0.00	\$0.00
Total Estimate:		\$0.00	0.00	\$0.00	0.00	\$0.00	\$0.00
Grand Total:							\$0.00

Charge Date	Description	Amount
08/03/2023	Transportation	181.14
08/03/2023	Tag disposition	11.00
08/03/2023	Auto ims	16.00
08/03/2023	Full detail	125.00
Total Charges:		\$333.14



Photo left rear



Photo right rear



Photo right front



Photo interior



Photo dash



Photo engine





Photo odometer



Extra photo 4



Extra photo 5



Extra photo 6



Extra photo 7



Photo deck




Photo vin/id sticker



Left rear seat



Keys



Door panels



Deck lid badge



Front bumper cover chipped



Windshield cracked



Left drip rail peeling



Rr door chipped



Lf seat cushion stained



Rf seat cushion stained



Lr seat cushion stained